

## **AVIC-F310BT - CHANGE HISTORY**

### **Ver. 1.0003**

- Fixes that in some specific conditions the touch panel is inoperative (display seems frozen)

### **Ver. 1.0001**

- General UI improvement.
- Improvement on Eco function via NavGate Feeds.
- Improvement on "Call POI" function.